


AV 27

Giunzione intermedia passaparete

Bulkhead union

Union traversée de cloison

Gerade Schott



Type	OD1	D2	L1	L2	H1	g
27 04 04	4	M12x1	28	11	16	24,0
27 06 06	6	M14x1	34	16	18	34,5
27 08 08	8	M16x1	34	16	20	40,0
27 10 10	10	M18x1	39	19	22	51,0
27 12 12	12	M20x1	41	20	24	59,5


AV 28

Gomito intermedio

Union elbow

Raccord à coude

Winkelverschraubung



Type	OD1	D2	L1	g
28 04 04	4	9	17,5	8,5
28 06 06	6	12	20,5	16,5
28 08 08	8	14	22,5	22,5
28 10 10	10	16	25	28,5
28 12 12	12	19	26,5	43,5


AV 29

T intermedio

Union T

T égal

T-Verschraubung



Type	OD1	D2	L1	L2	g
29 04 04	4	9	17,5	35	11,0
29 06 06	6	12	20	40	22,0
29 08 08	8	14	21	42	28,0
29 10 10	10	16	24,5	49	37,5
29 12 12	12	19	26	52	53,0